

Trade name: Paint Marker Status: 23.11.2010
Product no.: MMP20-A BLACK Version: 1.0.0 / GB

1.) <u>Identification of the substance/preparation and of the</u> company/undertaking

Identification of the substance or preparation

Trade name

Paint Marker

Use of the substance/preparation

Ink for stationery products

Company/undertaking identification

Address

Pentel Bürobedarf-Handelsgesellschaft mbH

Lademannbogen 143 22339 Hamburg

GERMANY

Telephone no. +49 (0) 40 / 53 80 91 - 0 Fax no. +49 (0) 40 / 53 85 58 - 7

Information provided by / telephone

+49 (0) 40 / 53 80 91 - 0

Emergency telephone

For medical advice (in German and English): +49 (0)551 192 40 (Giftinformationszentrum Nord)

Advice on Safety Data Sheet

sdb info@umco.de

2.) Hazards identification

Classification

R10 Flammable.

Hazard symbols

- NONE

R phrases

10 Flammable.

3.) Composition / information on ingredients

Hazardous ingredients

2-methoxy-1-methylethyl acetate

EC no. 203-603-9 Index no. 607-195-00-7 CAS no. 108-65-6 Concentration > 50 < 70 %-b.w.

Classification R10

Hazard symbols - R phrases 10

ETHYLCYCLOHEXANE

EC no. 216-835-0 Index no. - CAS no. 1678-91-7

Concentration > 10 < 30 %-b.w.

Classification F; R11 Xn; R65

Hazard symbols F, Xn R phrases 11-65

cellulose nitrate

EC no. - Index no. 603-037-01-3 CAS no. 9004-70-0

Concentration > 5 < 10 %-b.w.

Classification F; R11

Hazard symbols F R phrases 11



Trade name: Paint Marker Status: 23.11.2010
Product no.: MMP20-A BLACK Version: 1.0.0 / GB

CARBON BLACK

EC no. 215-609-9 Index no. - CAS no. 1333-86-4

Concentration > 5 < 10 %-b.w.

Classification -

Hazard symbols R phrases -

4.) First aid measures

General information

In case of persisting adverse effects, consult a physician. Remove contaminated clothing and shoes immediately, and launder thoroughly before reusing.

After inhalation

Remove affected person from the immediate area. Ensure supply of fresh air.

After skin contact

Wash off immediately with soap and water. Do NOT use solvents or thinners!

After eye contact

Separate eyelids, wash the eyes thoroughly with water (15 min.). Seek medical assistance.

After ingestion

Do not induce vomiting. Summon a doctor immediately. Never give anything by mouth to an unconscious person.

5.) Fire-fighting measures

Suitable extinguishing media

Alcohol-resistant foam; extinguishing powder; Carbon dioxide; Water spray jet

Extinguishing media that must not be used for safety reasons

Full water jet

Special exposure hazards arising from the substance or preparation itself, combustion products, resulting gases

In the event of fire, the following can be released: Carbon dioxide (CO2); Carbon monoxide (CO)

Special protective equipment for fire-fighters

Use self-contained breathing apparatus. Wear protective clothing.

Other information

Cool endangered containers with water spray jet. Suppres gases/vapours/mists with water spray jet.

6.) Accidental release measures

Personal precautions

Refer to protective measures listed in sections 7 and 8. Ensure adequate ventilation. Keep away sources of ignition. Do not inhale vapours. Avoid contact with skin, eyes and clothing.

Environmental precautions

Do not discharge into the drains/surface waters/groundwater.

Methods for cleaning up/taking up

Take up with absorbent material (e.g., sand, kieselguhr, universal binder). Send in suitable containers for recovery or disposal.

7.) Handling and storage

Handling

Advice on safe handling

Provide good ventilation of working area (local exhaust ventilation, if necessary). If workplace exposure limits are exceeded, respiratory protection approved for this particular job must be worn. Product



Trade name: Paint Marker Status: 23.11.2010
Product no.: MMP20-A BLACK Version: 1.0.0 / GB

inherent handling risks must be minimised taking the appropriate measures for protection and preventive actions. The working process should be designed to rule out the release of hazardous substances or skin contact as far it is possible by the state of the art.

Advice on protection against fire and explosion

Vapours can form an explosive mixture with air. Take precautionary measures against static charges. Keep away from sources of heat and ignition.

Storage

Requirements for storage rooms and vessels

Containers which are opened must be carefully resealed and kept upright to prevent leakage. Always keep in containers of same material as the original one.

Advice on storage assembly

None known

Further information on storage conditions

Keep container tightly closed and dry in a cool, well-ventilated place. Protect from heat and direct sunlight.

8.) Exposure controls / personal protection

Exposure limit values

2-methoxy-1-methylethyl acetate

CAS no.	108-65-6
EC no.	203-603-9

2000/39/EWG

2-Methoxy-1-methylethylacetate

TWA	275	mg/m³	50	ml/m³
STEL	550	mg/m³	100	ml/m³

Skin resorption / Skin

sensibilisation

List of approved workplace exposure limits (WELs) / EH40

1-Methoxypropylacetate

TWA	274	mg/m³	50	ml/m³
STEL	548	mg/m³	100	ml/m³

Skin resorption / Sk

sensibilisation

CARBON BLACK

CAS no. 1333-86-4 EC no. 215-609-9

List of approved workplace exposure limits (WELs) / EH40

Carbon black

TWA 3,5 mg/m³ STEL 7 mg/m³

Exposure controls

Personal protective equipment

Respiratory protection

If workplace exposure limits are exceeded, a respiration protection approved for this particular job must be worn. In case of aerosol and mist formation, take appropriate measures for breathing protection in the event workplace threshold values are not specified.

Hand protection

Sufficient protection is given wearing suitable protective gloves checked according to i.e. EN 374, in the event of risk of skin contact with the product. Before use, the protective glove should be tested in any case for its specific work-station suitability (i.e. mechanical resistance, product compatibility and



Trade name: Paint Marker Status: 23.11.2010
Product no.: MMP20-A BLACK Version: 1.0.0 / GB

antistatic properties). Adhere to the manufacturer's instructions and information relating to the use, storage, care and replacement of protective gloves. Protective gloves shall be replaced immediately when physically damaged or worn. Design operations thus to avoid permanent use of protective gloves.

Eye protection

Safety glasses with side protection shield (EN 166)

Skin protection

Normal chemical work clothing.

General protective and hygiene measures

Do not eat, drink or smoke during work time. Keep away from foodstuffs and beverages. Avoid contact with eyes and skin. Remove soiled or soaked clothing immediately. Do not inhale vapours. Clean skin thoroughly after work; apply skin cream.

9.) Physical and chemical properties

General information

Form liquid

Colour product specific Odour solvent-like

Important health, safety and environmental information

Changes in physical state

Type Value	Boiling point 131,8		°C
Flash point Value	23,9		°C
Density Value Reference temperature	0,94 20	° C	g/cm³
Viscosity Type Value	dynamic 25		mPa*s
Reference temperature Type	20 kinematic	°C	
Value Reference temperature	27,0 20	° C	mm²/s

10.) Stability and reactivity

Conditions to avoid

Protect from sun.

Materials to avoid

None known.

Hazardous decomposition products

No hazardous decomposition products known.

11.) <u>Toxicological information</u>

Experience in practice

Inhalation of solvent vapours in higher concentration may lead to nausea, headache, drowsiness and dizziness. Repeated and prolonged skin contact may cause removal of natural fat from the skin and irritation of the skin. Irritating to eyes.

Pentel.

Trade name: Paint Marker Status: 23.11.2010
Product no.: MMP20-A BLACK Version: 1.0.0 / GB

Other information (chapter 11.)

Product specific toxicological data are not known.

12.) Ecological information

Other information

Ecological data are not available. Do not discharge product unmonitored into the environment.

13.) <u>Disposal considerations</u>

Product

Allocation of a waste code number, according to the European Waste Catalogue, should be carried out in agreement with the regional waste disposal company.

Packaging

Residuals must be removed from packaging and when emptied completely disposed of in accordance with the regulations for waste removal. Incompletely emptied packaging must be disposed of in the form of disposal specified by the regional disposer.

14.) <u>Transport information</u>

Transport ADR/RID/ADN

Class	3
Classification code	F1
Packing group	III
Hazard identification no.	30
UN number	1263
Technical name	PAINT
Special Provision 640	640E
Tunnel restriction code	D/E
Label	3

Transport IMDG

Class	3
Packing group	Ш
UN number	1263
Proper shipping name	PAINT
EmS	F-E+S-E
Label	3

Transport ICAO/IATA

Class 3
Packing group III
UN number 1263
Proper shipping name Paint
Label 3

15.) Regulatory information

Labelling in accordance with EC directives

The product is classified and labelled in accordance with EC Directive 1999/45/EC.

The data subject of this Material Safety Data sheet refer to the ink contained in this product (marker).

Hazard symbols

- NONE

Pentel:

Trade name: Paint Marker Status: 23.11.2010
Product no.: MMP20-A BLACK Version: 1.0.0 / GB

R phrases

10 Flammable.

S phrases

2 Keep out of the reach of children.

Council Directive 96/82/EC on the control of major-accident hazards involving dangerous

substances

Remarks Annex I, part 2, category 6

16.) Other information

Relevant R-phrases (chapter 3):

10 Flammable.11 Highly flammable.

65 Harmful: may cause lung damage if swallowed.

Department issuing safety data sheet

UMCO Umwelt Consult GmbH

Georg-Wilhelm-Str. 183 b, 21107 Hamburg, Germany

Tel.: +49 40 / 41 92 13 00 Fax: +49 40 / 41 92 13 57 e-mail: umco@umco.de

This information is based on our present state of knowledge. However, it should not constitute a guarantee for any specific product properties and shall not establish a legally valid relationship.